


PLAN VIEW



PROFILE VIEW

NOTES

- 1. CUT AND PLUGS MUST BE ADEQUATELY "DRY BLOCKED".
- 2. DRY BLOCKS SHALL BE STANDARD SIZE SOLID MASONRY CONCRETE BLOCKS. (ASTM C-139)
- 3. THE QUANTITY AND ARRANGEMENT OF THE BLOCKING MUST WITHSTAND LINE PRESSURE BY HOLDING THE CAP OR PLUG IN POSITION.
- 4. DRY BLOCKING SHALL BE PROPERLY SHIMMED TIGHT AND SECURE AGAINST THE CAP BEFORE LINE PRESSURE IS RESTORED.
- 5. CONCRETE THRUST BLOCKS SHALL NOT BE POURED UNTIL LINE PRESSURE IS RESTORED AND THE CAP OR PLUG IS INSPECTED FOR LEAKAGE.
- 6. CONCRETE SHALL NOT BE POURED OVER ANY PORTION OF THE ABANDONED PIPE.
- 7. MINIMUM THRUST BLOCK AREA PER M.A.G. DETAIL 380.
- 8. WHERE A 4" OR LARGER LINE IS SPECIFIED TO BE ABANDONED, CUT AND PLUG SHOULD OCCUR AT THE SUPPLY MAIN TO AVOID CREATING AN UNUSED DEADEND LINE.

DETAIL NO. **G-3305**